

1. One role of a metrologist is to:
  - a. Develop the quality manual
  - b. Calibrate inspection instruments
  - c. Create the inspection report
  - d. Make accept or reject decisions
  
2. One role of an inspector is to:
  - a. Create the measurement plan
  - b. Develop the quality manual
  - c. Implement the measurement plan
  - d. Determine what relationships to measure
  
3. In this course, the definition for the term “quality” involves:
  - a. Having near nominal precision
  - b. Conformance to specifications
  - c. Being of superior characteristics
  - d. Having a high capability index - CpK
  
4. Inspection is important because it ensures that:
  - a. Engineering designs are complete
  - b. Correct processes are in place
  - c. Customers are satisfied
  - d. None of the above

5. Which is not a part of a quality manual?
- Defining the responsibility of each department
  - Defining training and qualification requirements of inspectors
  - Defining sample sizes and frequency of inspections
  - Defining the means of distribution
6. Metrology is:
- The study of a part's dimensional variations
  - The process of implementing the measurement plan
  - The science of measurement and its application
  - The practice of using judgment to determine if parts pass or fail
7. Inspection is:
- The practice of providing oversight for manufacturing process variations over time
  - The process of creating the measurement plan and determining measurement uncertainty
  - The practical aspects of measurement and uncertainty as directed by the quality manual
  - The process of measuring or otherwise comparing part characteristics to drawing specifications

8. The four types of inspection are final, process, receiving, and:
- Partial
  - Preliminary
  - Secondary
  - Batch
9. The purpose of a quality manual is to define responsibilities and authorities for:
- The plant
  - Inspectors
  - The quality system
  - Inspection
10. An inspector:
- Conducts tests
  - Calibrates equipment
  - Creates measurement plans
  - None of the above

SAE International - Not for Distribution

1. The smallest change in a quantity being measured that causes a perceptible change in the corresponding indication is called:
  - a. Accuracy of an instrument
  - b. Precision of an instrument
  - c. Resolution of an instrument
  - d. None of the above
  
2. Where measurement uncertainty is estimated using statistical methods, it is referred to as:
  - a. Type A
  - b. Type B
  - c. Expanded
  - d. Combined
  
3. What does measurement uncertainty mean?
  - a. Doubt about how to measure
  - b. Doubt about the measurement result
  - c. Doubt about where to measure
  - d. None of the above

4. Understanding the amount of uncertainty is important because it allows:
- a. Guard bands to be optimized
  - b. Inspectors to do a better job
  - c. More good parts to pass inspection
  - d. None of the above
5. What is the definition of “measurand”?
- a. The result of a measurement
  - b. Parameter of a measurement
  - c. A quantity intended to be measured
  - d. None of the above
6. Common contributors to measurement uncertainty are the operator, the drawing specification, and:
- a. Part
  - b. The drawing creator
  - c. Calculation errors made by the inspector
  - d. None of the above

7. Physical differences contribute to which measurement uncertainty category?
- Environment
  - Measurement setup
  - Measurement equipment
  - Operator
8. What is a decision rule?
- A documented rule describing how uncertainty is allocated in measurements
  - A documented policy describing when deviations are appropriate
  - A policy to guide inspectors in documenting measured values
  - None of the above
9. The choice of a decision rule is based on:
- The ability to rework nonconforming parts
  - Measurement equipment resolution
  - Management acceptance of missed quotas
  - Cost of rejecting in tolerance parts vs. cost of acceptance out-of-tolerance parts

10. A guard band contains:
- a. The uncertainty of the measurement
  - b. The allowable tolerance
  - c. A safety factor
  - d. None of the above
11. What is a simple rejection?
- a. The rejection zone consists of all values inside the guard band
  - b. Measurements inside this zone are rejected even if they are inside the specification
  - c. The rejection zone consists of all values outside of the specification zone
  - d. None of the above
12. The location and decision outcome of any \_\_\_\_\_ must be documented in the decision rule.
- a. Relaxed acceptance zone
  - b. Relaxed rejection zone
  - c. Transition zone
  - d. None of the above

13. The resolution of the measurement equipment is important for:
- Calculating uncertainty
  - Establishing gage R& R values
  - Selecting the decision rule
  - None of the above
14.  T  F Simple rejection means any measurement result that lies outside of the specification zone may be rejected.
15.  T  F Relaxed acceptance with stringent rejection is one of the four decision rules.
16.  T  F A decision rule must document the location of the acceptance, rejection, and transition zones.
17.  T  F Using the stringent acceptance rule lowers manufacturing cost.
18.  T  F A decision rule must include a decision for any measurement result that lies within the transition zone.



1. The three categories of inspection tools are:
  - a. GO/NOGO, functional, and feeler
  - b. Attribute, variables, and algorithmic
  - c. Touch, non-contact scanning, and vision
  - d. None of the above
  
2. Which type of measurement provides a measured value directly from the inspection tool?
  - a. Attribute
  - b. Functional
  - c. Algorithmic
  - d. None of the above
  
3. Which inspection tool is commonly used to make an attribute measurement?
  - a. Laser tracker
  - b. Calipers
  - c. Air gage
  - d. Plug gage

SAE International - Not for Distribution

4. A variable measurement may be affected by:
- Class of tolerance
  - Tolerance accumulation
  - Fixture loads
  - Excessive play
5. A digital micrometer is typically considered to be what type of inspection tool?
- Attribute
  - Variables
  - Algorithmic
  - None of the above
6. A “least squares” algorithm is commonly used with:
- A CMM
  - A digital height gage
  - An optical comparator
  - None of the above

SAE International - Not for Distribution

7. A basic operating principle of an attribute gage is that the gage should:
- a. Go into or over the part feature without excessive force
  - b. Be made of the same material as the part
  - c. Never reject a good part
  - d. None of the above
8. What is a basic principle of algorithmic type inspection tools?
- a. They are faster than attribute or variable measurement tools
  - b. They require the part to be clamped to the table for inspection
  - c. They collect a set of data points
  - d. None of the above
9. What is a basic principle of variable measurement type inspection tools?
- a. They require a skilled operator to align or orient the measurement device to the workpiece correctly
  - b. They are used to collect a set of data points for use in an algorithm
  - c. They are not affected by Abbe error, backlash, or friction
  - d. None of the above

10. An optical comparator is commonly considered to be what type of inspection tool?
- Algorithmic
  - Attribute
  - Variable measurement
  - Both B and C
11.  T  F A ring gage is a type of attribute inspection tool.
12.  T  F Attribute data includes a value of the measurement.
13.  T  F The tolerance policy used for a functional gage should be stated in the measurement plan.
14.  T  F An algorithmic measurement device costs less than a variable measurement device.
15.  T  F An optical comparator is often used as an attribute measurement device.

1. Which Y14.5 concept supports the use of an attribute gage?
  - a. Bonus tolerance
  - b. RMB
  - c. Position tolerance
  - d. None of the above
  
2. How is a round hole of a workpiece simulated in a functional gage?
  - a. With a conical-shaped pin
  - b. With a diamond-shaped pin
  - c. With a set of two opposed points
  - d. With a full-form cylindrical pin
  
3. An attribute gage cannot be used to verify which geometric attributes?
  - a. Rule #1 boundary
  - b. Location of a feature of size
  - c. Orientation of a feature
  - d. None of the above

SAE International - Not for Distribution

4. Which gage tolerancing policy accepts a few bad parts but rejects no good parts?
- a. Absolute tolerancing policy
  - b. Optimistic tolerancing policy
  - c. Tolerant tolerancing policy
  - d. None of the above
5. Using the absolute tolerancing policy on a functional gage, the gage tolerances are:
- a. Subtracted from the specification limits
  - b. Added to the specification limits
  - c. Added and subtracted from the specification limits
  - d. None of the above
6. The Y14.43 recommended tolerance for an attribute gage is:
- a. 10% gage tolerance and 10% wear allowance
  - b. 10% gage tolerance and 5% wear allowance
  - c. 5% gage tolerance and 5% wear allowance
  - d. None of the above

SAE International - Not for Distribution

7. When using the tolerant gage tolerancing policy, a functional gage will...
- Rejected all noncompliant parts
  - Accepted all compliant parts
  - Accept some noncompliant and reject some compliant parts
  - None of the above
8. The optimistic gage tolerancing policy places the gage tolerance \_\_\_\_\_ the specification limits.
- All outside
  - All inside
  - Half inside and half outside
  - None of the above
9. Which gage tolerancing policy is most likely to accept out-of-spec features?
- Absolute
  - Optimistic
  - Tolerant
  - Depends upon the class of gage tolerance

10. How much tolerance does a 50mm class 'X' gage pin get?
- a. 0.0019
  - b. 0.0023
  - c. 0.0050
  - d. None of the above
11. What is one result of using a class "Z" gage tolerance?
- a. Rejection of good parts decreases
  - b. Rejection of good parts increases
  - c. Gage cost increases
  - d. None of the above
12. A gage with a class X tolerance should be used to verify a workpiece feature with:
- a. Class H11 tolerance
  - b. Class H9 tolerance
  - c. Class H8 tolerance
  - d. Class H7 tolerance

SAE International - Not for Distribution



1. While a GO gage uses less than 10% of the design tolerance, a functional gage may actually use:
  - a. Up to 20%
  - b. Up to 30%
  - c. Up to 40%
  - d. Up to 50%
  
2. Which are design constraints of a functional gage?
  - a. The size and weight of the functional gage
  - b. The resolution of the indicator
  - c. A functional gage is only suitable for in-process inspection
  - d. None of the above
  
3. An in-process gage is a gage:
  - a. Used by manufacturing personnel to inspect the process
  - b. Used in a non-hostile environment
  - c. That has a gage tolerance more precise than a final inspection gage
  - d. Made by the manufacturing process

4. When is it acceptable to depart from the two opposed points LMC gaging principle with an attribute type gage?
  - a. On most attribute gages, flats may be used to avoid excessive wear
  - b. On very large holes
  - c. On large shaft diameters
  - d. None of the above
  
5. How does a datum feature referenced at RMB affect the gage design?
  - a. The datum feature simulator must be adjustable
  - b. The part cannot be displaced on the gage
  - c. The inspector can optimize the part position on the gage
  - d. Both A and B
  
6. Unless otherwise specified, workpieces are to be inspected:
  - a. In the restrained state, where necessary to make repeatable measurements
  - b. Only restrained against the datum features
  - c. In the same orientation as they'll be in the final assembly
  - d. Without any force at all (free state)

SAE International - Not for Distribution


7. Why is a referee gage necessary?
- Because inspectors may make errors when using unfamiliar gages
  - To mediate acceptance disputes from other gages
  - Because of the uncertainty in measurement
  - To calibrate the production gage
8. When is it permissible to depart from full-form, full-length MMC gage principles?
- When gaging an extremely long (deep) hole
  - When gaging an extremely small diameter
  - When gaging a flexible (non-rigid) part
  - None of the above
9. Using a 10% gage tolerance and absolute gaging policy, what size would the GO gage pin be for a 12.3-12.7 diameter hole?
- 12.30 – 12.34 dia.
  - 12.28 – 13.32 dia.
  - 12.26 – 12.30 dia.
  - None of the above

10. Using a 10% gage tolerance and the optimistic gaging policy, what size would the GO-ring gage be for a 54.2-54.7 diameter shaft?
- a. 54.675 – 54.725 dia.
  - b. 54.65 – 54.70 dia.
  - c. 54.75 – 54.80 dia.
  - d. None of the above

SAE International - Not for Distribution

Exercise 6 Solution


REVISIONS				
REV	DATE	DESCRIPTION	CHECK	APPROVED
A	7/21/2005	REVISED PER E.O. #071405	MA	AK



16 1. MATERIAL: SAE1006 2±0.08 THK 15  
UNLESS OTHERWISE SPECIFIED

NOTES:

UNLESS OTHERWISE SPECIFIED  
DIMENSIONS ARE IN MILLIMETERS  
TOLERANCES ARE:  
LINEAR ANGLES  
±0.5 ±5°  
DRAWING PER ASME Y14.5-2009



Effective Training Inc.

Spring Retainer

PROPRIETARY AND CONFIDENTIAL  
THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF  
EFFECTIVE TRAINING INC. ANY REPRODUCTION IN PART OR AS A WHOLE  
WITHOUT THE WRITTEN PERMISSION OF EFFECTIVE TRAINING INC. IS PROHIBITED.

MATERIAL: SEE NOTES	SIZE A	D/WG. NO. FN-106	REV. A8
DO NOT SCALE DRAWING	SCALE: 1:2	DATE: 5/8/2011	SHEET 1 OF 1

Dimensional Measurement Plan

Dimensional Measurement Plan Information											Page 1 of 2	
<input type="checkbox"/> Prototype <input checked="" type="checkbox"/> First Article <input type="checkbox"/> Production			Key Contact/Phone:				Date (Orig.):			Date (Rev.):		
Measurement Plan Number: <b>Exercise 6</b>						Core Team:			Customer Engineering Approval/Date (if Req'd):			
Part Number/Latest Change Level: FN-106 Rev A						Supplier/Plant Approval/Date:			Customer Quality Approval/Date (if Req'd):			
Part Name/Description: Spring retainer						Design Function Analysis #:			DFMEA#:			
Supplier/Plant:						Supplier Code:						
Dimensional Information						Methods				Measurement Conditions		
Dim No.	Description	MFG Process	MFG CpK	Special Char. Class	Specification/Tolerance	Evaluation Measurement Method	Sample		Measurement Equipment	Acceptable Limits	Decision Rule/Attribute Gage Tolerance Policy	
							Size	Freq.				
1	Flatness on datum feature A	N/A	N/A	N/A	0.2 max	Use flatness gage (surface plate with dial indicator mounted in hole)	N/A	N/A	Flatness gage #XXXXX	0-0.2	Simple acceptance rule 5:1	
2	Local size of hole	N/A	N/A	N/A	12.5 ±0.3	Measure two places 90° apart.	N/A	N/A	Digital calipers #XXXX	11.9-12.5	Simple acceptance rule 5:1	
3	Rule #1 on hole	N/A	N/A	N/A	12.2	Use GO-plug gage	N/A	N/A	GO Gage #XXXXX	Pass	Absolute gaging policy	
4	Perpendicularity to datum A	N/A	N/A	N/A	∅12.1 VC	Use functional gage	N/A	N/A	Functional Gage (XXXX)	Pass	Absolute gaging policy	
5	Local size of O.D.	N/A	N/A	N/A	53.6 ±0.5	Measure two places 90° apart	N/A	N/A	Digital calipers #XXXX	53.1-54.1	Simple acceptance rule 4:1	
6	Rule #1 on O.D.	N/A	N/A	N/A	54.1	Use GO-ring gage	N/A	N/A	GO Gage #XXXXX	Pass	Absolute gaging policy	
7	Position of O.D.	N/A	N/A	N/A	∅54.9 VC	Use functional gage	N/A	N/A	Functional Gage (#XXXX)	Pass	Absolute gaging policy	
8	Local size of tower diameter	N/A	N/A	N/A	39.9 ±0.5	Measure two places 90° apart.	N/A	N/A	Digital calipers #XXXX	39.4-40.4	Simple acceptance rule 5:1	
9	Rule #1 on tower diameter	N/A	N/A	N/A	40.4	Use GO-ring gage	N/A	N/A	GO Gage #XXXXX	Pass	Absolute gaging policy	
10	Position of tower diameter	N/A	N/A	N/A	∅40.6 VC	Use functional gage	N/A	N/A	Functional Gage (#XXXX)	Pass	Absolute gaging policy	
11	Step dimension	N/A	N/A	N/A	17.9 ±0.5	1. Rest flanged surface of part on surface plate. 2. Measure distance from top surface of flange to top surface of part in 4 places 90° apart.	N/A	N/A	Surface plate, height gage	17.4-18.4	Simple acceptance rule 5:1	
12	Parallelism of flange	N/A	N/A	N/A	0.3 max	Check at least 18 points equally spaced	N/A	N/A	Surface plate Height gage (#xxxxx)	0.3 max	Simple acceptance rule 5:1	



Dimensional Measurement Plan

Dimensional Measurement Plan Information											Page 2 of 2	
<input type="checkbox"/> Prototype <input checked="" type="checkbox"/> First Article <input type="checkbox"/> Production			Key Contact/Phone:				Date (Orig.):		Date (Rev.):			
Measurement Plan Number: <b>Exercise 6</b>			Core Team:				Customer Engineering Approval/Date (If Req'd):					
Part Number/Latest Change Level: FN-106 Rev A			Supplier/Plant Approval/Date:				Customer Quality Approval/Date (If Req'd):					
Part Name/Description: Spring retainer			Design Function Analysis #:				DFMEA#:					
Supplier/Plant:			Supplier Code:									
Dimensional Information						Methods			Measurement Conditions			
Dim No.	Description	MFG Process	MFG CpK	Special Char. Class	Specification/Tolerance	Evaluation Measurement Method	Sample		Measurement Equipment	Acceptable Limits	Decision Rule/Attribute Gage Tolerance Policy	
							Size	Freq.				
13	Flange to tower radius	N/A	N/A	N/A	R1 max	Use radius gage template	N/A	N/A	Radius gage #XXXX	0-1	Absolute gaging policy	
14	Tower wall to bottom radius	N/A	N/A	N/A	R3 max	Use radius gage template	N/A	N/A	Radius gage #XXXX	0-3	Absolute gaging policy	
15	Stock thickness	N/A	N/A	N/A	2 ±0.08	1. Measure flange 2 places 180° apart. 2. Measure side wall 2 places 180° apart. 3. Measure bottom wall 4 places 90° apart.	N/A	N/A	Digital calipers #XXXX Need to identify a tool for steps 2 & 3.	1.92-2.08	Simple acceptance rule 5:1	
16	Material	N/A	N/A	N/A	SAE 1060	Verify material certification	N/A	N/A				

SAE International - Not for Distribution

1. T  F An inspection report establishes the plan for how to inspect the part.
2.  T F One requirement of an inspection report is to correlate the measurements to the print dimensions.
3. T  F On large complex drawings, numbering dimensions may be omitted to keep the drawing clear.
4.  T F Where an attribute gage is used, the inspection report does not report numbers or magnitude.
5. T  F A nonconformance report should be an internal document not shared with the customer.
6. The practice of numbering dimensions and tolerances for inspection aids in:
  - a. Ensuring that all dimensions are identified for inspection
  - b. Identifying the proper algorithm for inspection
  - c. Choosing the best inspection tool
  - d. Identifying tolerances that are overly restrictive
7. When numbering a size dimension that applies to a pattern of holes, the dimension is assigned a base number and:
  - a. The base number applies to all of the holes
  - b. Each hole in the pattern is assigned a sub-number
  - c. Each hole in the pattern is assigned a different base number
  - d. The holes in the pattern are not assigned any number



8. A nonconformance report documents the \_\_\_\_\_ for a workpiece that failed the gaging or had a measurement outside its tolerance specification.
- Gage R&R
  - Measurement procedure used
  - Corrective action
  - Nonconformity costs
9. An inspection report may display the results of a measurement by using:
- Marks on the drawing
  - Color coding
  - A signed certificate of approval
  - Special symbols
10. A standard format for inspection reports is:
- ASME Y14.5.1
  - ASME Y14.43
  - APQP
  - AS9102A

SAE International - Not for Distribution

1. Which algorithm is most accurate when inspecting the Rule #1 requirement of a hole?
  - a. Least squares best fit cylinder
  - b. Maximum inscribed cylinder
  - c. Minimum circumscribed cylinder
  - d. Minimum zone cylinder
  
2. Which method is most accurate when inspecting the Rule #1 requirement of a hole?
  - a. A GO-snap gage
  - b. A GO-ring gage
  - c. A GO-plug gage
  - d. A caliper
  
3. Which method or gage may be used to inspect the LMC size limit of a shaft diameter?
  - a. A NOGO-snap gage
  - b. A CMM using the minimum circumscribe algorithm
  - c. A CMM using the least squares algorithm
  - d. None of the above

SAE International - Not for Distribution

4. When inspecting the Rule #1 requirement of a shaft diameter, what is reported?
- a. Pass or fail results of the diameter fitting a GO-ring gage
  - b. Maximum measured actual local size
  - c. Set of all measured actual local sizes
  - d. None of the above
5. When inspecting the LMC size limit of a shaft diameter, what is reported?
- a. Maximum measured actual local size
  - b. Set of all measured actual local sizes
  - c. Minimum measured actual local size
  - d. None of the above
6. When is Rule #1 not inspected?
- a. When inspecting a regular feature of size to which a position tolerance applies
  - b. When inspecting a regular feature of size to which a perpendicularity tolerance applies
  - c. When inspecting the thickness of 16 GA sheet metal
  - d. None of the above

7. Which statement is true when using an attribute gage to inspect an actual local size?
- a. It requires two gages: one for the max size limit and one for the min size limit
  - b. The gage should not be a full-length, full-form gage
  - c. Both A & B
  - d. None of the above
8. When using a CMM to inspect the size of a hole, which algorithm complies with the Y14.5 definition of an actual local size?
- a. Least squares best fit circle
  - b. Minimum circumscribed circle
  - c. Maximum inscribed circle
  - d. None of the above
9. When inspecting an internal regular feature of size, what should be indicated on the inspection report?
- a. The pass or fail results for Rule #1
  - b. The largest actual local size measurement
  - c. Both A & B
  - d. None of the above

10. When using a CMM to inspect Rule #1 on a shaft with an anticipated form error greater than 10% of size tolerance, what is the suggested minimum number of points needed?
- a. 20 equally spaced points on four equally spaced circular elements
  - b. 28 equally spaced points on at least 4 equally spaced circular elements
  - c. 80 equally spaced points on four equally spaced circular elements
  - d. None of the above

SAE International - Not for Distribution

1.  T  F A candidate datum set is the set of all possible datums established from a datum feature.
2.  T  F Any one of the qualified candidate datums may be used for inspection.
3.  T  F A datum plane is always established from the largest surface on the part.
4.  T  F Form variations on the datum features may cause a part with all planar datums to have more than one orientation in its datum reference frame.
5.  T  F If a part does not meet a requirement on one candidate datum, but does meet the requirement on another, the part is considered to have passed the requirement.
6.  T  F One way to reduce the effects a candidate datum set has on inspection is to specify a flatness tolerance on the primary datum feature.
7.  T  F Using the candidate datum set concept increases measurement uncertainty.
8.  T  F Specifying datum targets will eliminate the candidate datum set.
9.  T  F Using the candidate datum set will reduce the amount of parts that are accepted.

10. Which drawing indication communicates how the part is located and oriented in a gage or fixture during inspection?
- a. Datum reference sequence
  - b. Coordinate linear and angular dimensions
  - c. General (title block) tolerances
  - d. None of the above
11. A primary datum plane is a plane established from \_\_\_\_\_ of the datum feature.
- a. The three highest points
  - b. A least squares plane passing through all points
  - c. The single highest point
  - d. The two highest points
12. A primary datum must constrain a minimum of \_\_\_\_ degrees of freedom.
- a. 2
  - b. 3
  - c. 4
  - d. 6

SAE International - Not for Distribution

13. If a primary planar datum feature is concave, it:
- a. Will only have one candidate datum plane
  - b. May have several candidate datum planes
  - c. Cannot be used as a primary datum feature
  - d. None of the above
14. One of the Y14.5 requirements for a datum feature is that it must be:
- a. Accessible
  - b. An external feature
  - c. Simulated in the restrained state for a flexible part
  - d. None of the above

SAE International - Not for Distribution



1.  T  F Using the proper probing strategies with CMM datum simulation reduces measurement uncertainty.
2.  T  F Failure to correctly simulate a datum reference frame may affect all geometric tolerances related to the datum reference frame.
3.  T  F A CMM operator should always probe the workpiece to simulate a datum reference frame.
4.  T  F A least squares cylinder should be used to establish a datum axis RMB.
5.  T  F Datum feature shift cannot be done when measuring with a CMM.
6. When simulating a primary datum plane with a CMM where the flatness of the surface is unknown, what is the suggested minimum number of points that should be taken?
  - a. 3
  - b. 9
  - c. 20
  - d. 500

7. When simulating a primary datum axis using a CMM where the form error of the diameter is unknown, what is the suggested minimum number of points that should be taken?
- a. 5
  - b. 28
  - c. 80
  - d. 160
8. When simulating a datum axis (primary RMB) with a functional fixture, the candidate datum set concept:
- a. Does not apply
  - b. Does apply
  - c. Only applies if the part is non-rigid
  - d. Only applies if the part not restrained
9. When using a CMM to simulate a primary datum axis (RMB) from a hole which algorithm should be used?
- a. Least squares best fit cylinder
  - b. Minimum circumscribed cylinder
  - c. Maximum inscribed cylinder
  - d. None of the above

1. What is the Y14.5 requirement of flatness?
  - a. That two planar surfaces are parallel
  - b. That the surface is not wavy or convex
  - c. The high and low points of a surface are limited by two parallel planes
  - d. The high and low points of each line are limited by two parallel lines
  
2. When using a CMM to inspect flatness of a workpiece, what is the algorithm that best matches the Y14.5 requirement?
  - a. Least squares
  - b. Minimum tangent plane
  - c. Minimum circumscribed
  - d. Minimum zone
  
3. What is one limitation of variable measurement inspection of flatness?
  - a. The part must be light enough for the inspector to manipulate
  - b. Algorithmic measurement is far more accurate
  - c. Open setup inspections of flatness are time consuming
  - d. Only attribute data can be collected
  
4. What is one benefit of variable measurement inspection of flatness?
  - a. The required equipment is relatively economical
  - b. The inspection is unaffected by small amounts of dirt
  - c. The resolution of the indicator has only a minimal effect on accuracy
  - d. The tip size of the indicator has only a minimal effect on accuracy

5. When using a CMM to inspect flatness on a surface with a form error greater than 10%, what is the recommended minimum number of points?
- 9
  - 25
  - 80
  - None of the above
6. When using the Ad Hoc probing strategy to distribute 80 points on a 20 x 60 mm surface, which grid pattern size should be used?
- 4 X 20
  - 8 X 10
  - 9 X 9
  - None of the above
7. What is the Y14.5 requirement for a flatness tolerance at MMC applied to a planar feature of size?
- The derived median plane must fit within two parallel planes
  - The two opposed surfaces must fit within a virtual condition boundary
  - Both opposed surfaces must fit with two parallel planes
  - None of the above

8. For a planar feature of size (width), its virtual condition may be simulated using:
- Two gage blocks spaced apart at the virtual condition distance
  - A mylar overlay on an optical comparator
  - Calipers set at the virtual condition size
  - None of the above
9. In a traditional inspection report, how is the measurement result of a flatness tolerance applied to a surface reported?
- Pass / fail result of the part fitting a GO gage
  - The value of the furthest point from a least squares plane
  - The max measured deviation between the highest and lowest points on the surface
  - None of the above
10. Which of these is an example of a computer-aided inspection report for a flatness tolerance applied to a surface?
- A CMM report showing the max measured deviation value
  - A color-coded surface topography map
  - A whisker plot
  - None of the above

1. In Y14.5, a straightness tolerance applied to a surface requires that:
  - a. All surface line elements are parallel
  - b. The surface is not wavy or convex
  - c. All points of a surface must be between two parallel planes
  - d. All points of each line element must be between two parallel lines
  
2. What is one option for variable measurement of straightness of a line element?
  - a. Set the part in a V-block, and run an indicator along the surface
  - b. Use an optical comparator to measure the distance from a line tangent to the highest or lowest points of a line element to the furthest point from the tangent line
  - c. Establish a least squares mid-line, and measure the distance between the furthest points on each side of that line
  - d. None of the above
  
3. What are the two most common algorithms used when inspecting straightness of a line element on a CMM?
  - a. Least squares and two-point measurement
  - b. Least squares and maximum tangent plane
  - c. Least squares and minimum zone
  - d. Least squares and minimum tangent plane

4. What is a common inspection method for straightness at MMC applied to a feature of size?
- A CMM & least squares algorithm
  - A GO Gage
  - A CMM and minimum zone algorithm
  - Surface plate and wire gage
5. Which symbol must be specified when a straightness tolerance is applied to a feature of size?
- Square symbol
  - LMC symbol
  - MMC symbol
  - Diameter symbol
6. In a traditional inspection report for a straightness tolerance applied to a surface line element, which value is reported?
- The average of all measured straightness deviations of all line elements
  - The distance between the single highest point and the lowest point
  - The distance between a least squares line and furthest point
  - The distance from a tangent line to the furthest point

7.  T    F    According to Y14.5, acceptance limits are treated as absolute values.
8.  T    F    Decision rules explain the difference between design tolerances and acceptance limits.
9.  T     F    When inspecting straightness of a pin surface element, the indicator is moved radially along the surface.
10.  T     F    When inspecting straightness of a surface element on a CMM, the line element must be set parallel to the surface plate.

SAE International - Not for Distribution



1. How does a circularity tolerance limit the lobing of a diameter?
  - a. By limiting all circular elements within one circular boundary
  - b. By limiting all circular elements between two concentric circles
  - c. By limiting all circular elements within one cylindrical boundary
  - d. By limiting all line elements between two coaxial cylinders
  
2. Why is it important to conduct dimensional measurement planning for a circularity tolerance?
  - a. There is no other way to indicate the filtering parameter
  - b. There is no other way to indicate the applied algorithm
  - c. There is no other way to indicate the stylus tip size
  - d. There is no other way to indicate the number of surface points
  
3. Why can't a part be automatically rejected if its runout deviation is greater than its circularity tolerance using the circular runout method?
  - a. Because of the roundness deviation of the centers and center holes
  - b. Because of the straightness deviation of the part
  - c. Because the runout measurement includes the eccentricity of the circular element to the axis of rotation
  - d. Because of the misalignment of the centers on the gage

4. When inspecting circularity using a precision spindle machine, what is the algorithm that best matches the Y14.5 definition of the tolerance zone?
- a. Minimum radial separation
  - b. Least squares circle
  - c. Minimum circumscribed circle
  - d. Maximum inscribed circle
5. When inspecting circularity of a 12mm diameter, what is the default UPR filtering?
- a. 15
  - b. 30
  - c. 50
  - d. 100
6. What is one way to reduce specification uncertainty with circularity?
- a. Conduct design reviews that include manufacturing and quality personnel
  - b. Use the complete circularity specification
  - c. Conduct measurement planning for all parts
  - d. Use established standards

7. When using an algorithmic measurement method to inspect cylindricity, how is the reference axis established?
- By locating the part on centers in a fixture
  - By using a chuck, collet, or other centering device
  - By using a minimum zone algorithm
  - None of the above
8. What is one source of uncertainty unique to using the total runout method to inspect cylindricity?
- The number of data points
  - The misalignment of the centers
  - The surface roughness of the diameter
  - The algorithm that is used
9. When using a CMM to inspect cylindricity, the applied algorithm:
- Should be specified as a complete cylindricity tolerance on the drawing
  - Should be specified in the inspection or non-conformance report
  - Should default to the algorithms defined in the ASME Y14.5 standard
  - Should be documented in the dimensional measurement plan

10. When using algorithmic measurement method to inspect a cylindricity tolerance, the measurement result is affected by:
- a. The number of data points
  - b. The applied algorithm
  - c. The shape of the part (e.g., hour glass, barrel, waisting, etc.)
  - d. All of the above

SAE International - Not for Distribution

1. What is one Y14.5 requirement of an angular dimension?
  - a. The high and low points of the surface must be within the tolerance zone
  - b. Only the high points of the surface must be within the tolerance zone
  - c. Only the low points of the surface must be within the tolerance zone
  - d. A tangent plane of each line element must be within the tolerance zone
  
2. When verifying an angular dimension, which method/tool is Y14.5 compliant?
  - a. A protractor
  - b. Applying the least squares algorithm
  - c. Applying the max tangent plane algorithm
  - d. None of the above
  
3. What is one Y14.5 requirement of a perpendicularity tolerance applied to a surface?
  - a. The tolerance zone must always be 90 degrees to the primary datum referenced
  - b. Only the high points of the part surface must be within the tolerance zone
  - c. Only the least squares plane of the part surface must be within the tolerance zone
  - d. The orientation of the tolerance zone is established from the high points of the part surface

4. When using a dial indicator to inspect a perpendicularity tolerance applied to a surface, the part is placed on the datum plane and the dial indicator is:
  - a. Moved vertically from the bottom to the top of the surface
  - b. Moved across the full length and width of the surface
  - c. Held stationary to check one point of the surface
  - d. None of the above
  
5. What is one source of measurement uncertainty when using a dial indicator to inspect a perpendicularity tolerance applied to a surface?
  - a. The shape of the tolerance zone
  - b. Whether the tangent plane or least squares algorithm is used
  - c. Probe tip size
  - d. None of the above
  
6. When using CMM to inspect a perpendicularity tolerance applied to a surface, the CMM calculates:
  - a. The distance between the highest and lowest points normal to a reference plane that is perpendicular to the datum plane
  - b. The angular deviation of a least squares plane of the toleranced surface
  - c. The angular deviation of a max or min tangent plane of the toleranced surface
  - d. None of the above

7. What is one source of measurement uncertainty when using a CMM to inspect a perpendicularity tolerance applied to a surface of a rigid part?
- The shape of the tolerance zone
  - The hardness of the part surface
  - The form deviation of the datum feature (e.g., convex surface)
  - None of the above
8. What is one Y14.5 requirement of a perpendicularity tolerance at MMC applied to a feature of size?
- It must be verified using variable-type measurement
  - The surface(s) of the feature of size must not violate a virtual condition boundary
  - The axis/center plane of the actual mating envelope must be within the tolerance zone
  - None of the above
9. What is the most common method/tool used to verify a perpendicularity tolerance at MMC applied to a feature of size?
- A protractor
  - A dial indicator
  - A functional gage
  - None of the above

10. What is one source of measurement uncertainty when using a functional gage to verify a perpendicularity tolerance at MMC applied to a feature of size?
- a. The shape of the tolerance zone
  - b. The form error of the feature of size
  - c. Tolerance accumulation within the gage
  - d. None of the above

SAE International - Not for Distribution



1. Which statement is a Y14.5 requirement for a position tolerance (RFS) applied to a hole?
  - a. The high and low points of the hole's surface must be within the tolerance zone
  - b. The axis of the unrelated actual mating envelope of the hole must be within the tolerance zone
  - c. The derived median line of the hole must be within the tolerance zone
  - d. A center point at each end of the hole must be within the tolerance zone
  
2. Which statement is a Y14.5 requirement of a position tolerance (MMC) applied to a hole?
  - a. The high and low points of the hole's surface must be within the tolerance zone
  - b. The surface of the hole must not violate a virtual condition boundary located at its true position
  - c. The derived median line of the hole must be within the tolerance zone
  - d. A center point at each end of the hole must be within the tolerance zone

SAE International Not for Distribution

3. When using a functional gage to inspect a position tolerance (MMC) applied to a hole, which step should be done first?
  - a. Measure the size of the hole and determine the amount of bonus tolerance available
  - b. Place a virtual condition pin into the hole
  - c. Locate the part relative to the datum reference frame
  - d. None of the above
  
4. What is one source of measurement uncertainty when using an attribute (functional) gage to inspect a position tolerance (MMC) applied to a hole?
  - a. The shape of the tolerance zone
  - b. How many points are taken on the hole surface
  - c. Probe tip size
  - d. None of the above
  
5. When verifying position tolerance (RFS) applied to a hole, the axis of the unrelated actual mating envelope may be simulated using:
  - a. A virtual condition gage pin
  - b. A best fit gage pin
  - c. An MMC gage pin
  - d. An LMC gage pin

6. Which of these choices is a source of measurement uncertainty when inspecting a position tolerance (RFS) applied to a hole using a variable measurement method?
- a. Location of the measurement
  - b. How many points are taken on the hole surface
  - c. The algorithm used
  - d. None of the above
7. When verifying position tolerance (RFS) applied to a hole using a CMM, the axis of the unrelated actual mating envelope may be simulated using a:
- a. Virtual condition gage pin
  - b. Least squares circle at each end of the hole
  - c. Max inscribed cylinder
  - d. None of the above
8. Which of these choices is a source of measurement uncertainty when inspecting a position tolerance (RFS) applied to a hole using a CMM?
- a. The shape of the tolerance zone
  - b. Including the effects of the bonus tolerance
  - c. Datum reference frame construction
  - d. None of the above

9. Which formula should be used to calculate the position tolerance deviation using the delta X and delta Y coordinates from true position?
- a.  $\frac{1}{2} (X * Y)$
  - b.  $2\sqrt{\Delta X^2 + \Delta Y^2}$
  - c.  $(\sum X - Y) / 2$
  - d. None of the above
10. When creating a dimensional measurement plan for a position tolerance (RFS), which item from the list below should be documented in the “measurement method” box of the form?
- a. Algorithm
  - b. Equipment ID
  - c. Sample size
  - d. None of the above

SAE International - Not for Distribution

1. Which statement describes a requirement from Y14.5 for a circular runout tolerance applied to a cylindrical surface?
  - a. The tolerance zone applies simultaneously to all circular elements of the surface
  - b. The tolerance zone is not related to any datums
  - c. The tolerance zone applies independently to each circular element
  - d. None of the above
  
2. Which statement describes a requirement from Y14.5 for a total runout tolerance applied to a cylindrical surface?
  - a. The tolerance zone applies simultaneously to all circular elements of the surface
  - b. The tolerance zone is not related to any datums
  - c. The tolerance zone applies independently to each circular element
  - d. None of the above

SAE International - Not for Distribution

3. Which statement best describes how to verify a circular runout tolerance using a dial indicator?
- a. An indicator contacts normal to the surface at a fixed location as the part is rotated about the datum axis
  - b. An indicator contacts normal to the surface and moves parallel to the datum axis as the part is rotated
  - c. An indicator contacts normal to the surface and moves parallel to the datum axis
  - d. None of the above
4. Which statement best describes how to verify a total runout tolerance using a dial indicator?
- a. An indicator contacts normal to the surface at a fixed location as the part is rotated about the datum axis
  - b. An indicator contacts normal to the surface and moves parallel to the datum axis as the part is rotated
  - c. An indicator contacts normal to the surface and moves parallel to the datum axis
  - d. None of the above

5. Which of these choices is a source of measurement uncertainty when using a dial indicator to inspect a circular runout tolerance applied to a cylindrical surface?
- a. Instrument resolution
  - b. How many points are taken on the surface
  - c. The algorithm used
  - d. None of the above
6. When using a CMM to inspect a total runout tolerance, the CMM calculates and reports the:
- a. Max distance between the datum axis and the center point of a least squares circle at several cross sections
  - b. Maximum radial deviation between highest and lowest point out of all measured circular cross sections
  - c. Radial distance between the furthest point and closet point to the datum axis for the full length and circumference of the surface
  - d. None of the above
7. Which of these choices is a source of measurement uncertainty when using a CMM to inspect a circular runout tolerance applied to a cylindrical surface?
- a. Datum axis simulation
  - b. Instrument resolution
  - c. Tolerance zone shape
  - d. None of the above

8. When creating a dimensional measurement plan for a runout tolerance, which item from the list below should be documented in the “measurement method” box of the form?
- a. Frequency
  - b. Equipment ID
  - c. Sample size
  - d. None of the above

SAE International - Not for Distribution



1. Which statement is a requirement of Y14.5 for a profile of a surface tolerance applied to a surface?
  - a. The tolerance zone is a three-dimensional boundary
  - b. The tolerance zone is a two-dimensional boundary
  - c. The tolerance zone is a one-dimensional boundary
  - d. None of the above
  
2. When verifying a profile tolerance, an attribute gage can be used to verify:
  - a. How much the surface varies from its true profile
  - b. If the surface is within the profile tolerance zone
  - c. How much the surface varies from its true position
  - d. None of the above
  
3. When using a functional gage to inspect a profile of a surface tolerance applied to a surface, which step should be done first?
  - a. Use a gage pin to determine if the surface is within the tolerance zone
  - b. Locate the part relative to its true profile
  - c. Locate the part relative to the datum reference frame
  - d. None of the above

4. When using an indicator to verify a profile of a surface tolerance, the dial indicator checks the location of the surface relative to the:
- a. True profile
  - b. Extreme boundaries
  - c. Profile tolerance value
  - d. None of the above
5. What is one source of measurement uncertainty when using variable measurement methods to inspect a profile tolerance applied to a surface?
- a. The shape of the tolerance zone
  - b. Probe tip size
  - c. The algorithm used
  - d. None of the above
6. When using a CMM to verify a profile of a surface tolerance, the CMM uses an algorithm to determine the:
- a. True profile of the surface
  - b. Location of the surface
  - c. Profile tolerance value
  - d. None of the above

7. Which of these choices is a source of measurement uncertainty when using algorithmic measurement methods to inspect a profile tolerance applied to a surface?
- a. The shape of the tolerance zone
  - b. Resolution of the indicator
  - c. Datum reference frame simulation
  - d. None of the above
8. When creating a dimensional measurement plan for a profile tolerance, which item from the list below should be documented in the “measurement method” box of the form?
- a. The shape of the tolerance zone
  - b. Number and spacing of points
  - c. Sample size
  - d. None of the above

SAE International - Not for Distribution