# Mechanics Modeling of Sheet Metal Forming

List of Chapters


Preface

1. Introduction to Typical Automotive Sheet Metal Forming Processes
   - 1.1 Stretching and Drawing
   - 1.2 Trimming
   - 1.3 Flanging and Hemming
   - 1.4 References

2. Tensor, Stress, and Strain
   - 2.1 Transformation of Vectors and Tensors in Cartesian Coordinate Systems
   - 2.2 Transformation of Vectors and Tensors in General Coordinate Systems
   - 2.3 Stress and Equilibrium
   - 2.4 Principal Stresses and Stress Invariants
   - 2.5 Finite Deformation Kinematics
   - 2.6 Small Strain Theory
   - 2.7 Different Stress Tensors
   - 2.8 Stresses and Strains from Tensile Tests
   - 2.9 Reference

3. Constitutive Laws
   - 3.1 Linear Elastic Isotropic Materials
   - 3.2 Linear Elastic Anisotropic Materials
   - 3.3 Different Models for Uniaxial Stress-Strain Curves
   - 3.4 Yield Functions Under Multiaxial Stresses
     - 3.4.1 Maximum Plastic Work Inequality
     - 3.4.2 Yield Functions for Isotropic Materials
       - 3.4.2.1 von Mises Yield Condition
       - 3.4.2.2 Tresca Yield Condition
       - 3.4.2.3 Plane Stress Yield Conditions for Isotropic Materials
     - 3.4.3 Yield Functions for Anisotropic Materials
       - 3.4.3.1 Hill Quadratic Yield Condition for Orthotropic Materials
       - 3.4.3.2 A General Plane Stress Anisotropic Yield Condition
   - 3.5 Evolution of Yield Surface
   - 3.6 Isotropic Hardening Based on the von Mises Yield Condition
   - 3.7 Anisotropic Hardening Based on the von Mises Yield Condition
   - 3.8 Isotropic Hardening Based on the von Mises Yield Condition with Rate Sensitivity
   - 3.9 Isotropic and Anisotropic Hardening Based on the Hill Quadratic Anisotropic Yield Condition
   - 3.10 Plastic Localization and Forming Limit Diagram
   - 3.11 Modeling of Failure Processes
   - 3.12 References

4. Mathematical Models for Sheet Metal Forming Processes
   - 4.1 Governing Equations for Simulation of Sheet Metal Forming Processes
   - 4.2 Equations of Motion for Continua
   - 4.3 Equations of Motion in Discrete Form
     - 4.3.1 Internal Nodal Force Vector
     - 4.3.2 External Nodal Force Vector
     - 4.3.3 Contact Nodal Force Vector
     - 4.3.4 Mass and Damping Matrices
     - 4.3.5 Equations of Motion in Matrix Form
   - 4.4 Tool Surface Models
   - 4.5 Surface Contact with Friction
     - 4.5.1 Formulation for the Direct Method
     - 4.5.2 Formulation for the Lagrangian Multiplier Method
     - 4.5.3 Formulation for the Penalty Method
   - 4.6 Draw-Bead Model
     - 4.6.1 Draw-Bead Restraint Force by Computation
     - 4.6.2 Draw-Bead Restraint Force by Measurement
   - 4.7 References

5. Thin Plate and Shell Analyses
   - 5.1 Plates and General Shells
   - 5.2 Assumptions and Approximations
   - 5.3 Base Vectors and Metric Tensors
   - 5.4 Lagrangian Strains

5.5 Classical Shell Theory
- 5.5.1 Strain-Displacement Relationship
- 5.5.2 Principle of Virtual Work
- 5.5.3 Constitutive Equation for the Classical Shell Theory
- 5.5.4 Yield Function and Flow Rule for the Classical Shell Theory
- 5.5.5 Consistent Material Tangent Stiffness Tensor
- 5.5.6 Stress Resultant Constitutive Relationship

5.6 Shell Theory with Transverse Shear Deformation
- 5.6.1 Constitutive Equation for the Shell Theory with Transverse Shear Deformation
- 5.6.2 Consistent Material Tangent Stiffness Tensor with Transverse Shear Deformation

5.7 References

**6. Finite Element Methods for Thin Shells**

6.1 Introduction
- 6.1.1 Computer-Aided Engineering (CAE) Requirements for Shell Elements
- 6.1.2 Displacement Method

6.2 Finite Element Method for the Classical Shell Theory—Total Lagrangian Formulation
- 6.2.1 Strain-Displacement Relationship in Incremental Forms
- 6.2.2 Virtual Work Due to the Internal Nodal Force Vector
- 6.2.3 Discretization of Spatial Variables in a Curved Triangular Shell Element
- 6.2.4 Increments of the Strain Field in Terms of Nodal Displacement Increments
- 6.2.5 Element Tangent Stiffness Matrix and Nodal Force Vector
- 6.2.6 Basic and Shape (Interpolation) Functions
- 6.2.7 Numerical Integration for a Curved Triangular Shell Element
- 6.2.8 Updating Configurations, Strains, and Stresses

6.3 Finite Element Method for a Shell with Transverse Shear Deformation—Updated Lagrangian Formulation
- 6.3.1 Strain-Displacement Relationship in Incremental Form
- 6.3.2 Virtual Work Due to the Internal Nodal Force Vector
- 6.3.3 Discretization of Spatial Variables in a Quadrilateral Shell Element
- 6.3.4 Increment of the Strain Field in Terms of Nodal Displacement Increments
- 6.3.5 Element Tangent Stiffness Matrix and Nodal Force Vector
- 6.3.6 Shape (Interpolation) Functions
- 6.3.7 Numerical Integration for a Quadrilateral Shell Element
- 6.3.8 Five to Six Degrees of Freedom per Node
- 6.3.9 Updating Configurations, Strains, and Stresses
- 6.3.10 Shear Lock and Membrane Lock

6.4 Discussion of $C^1$ and $C^0$ Continuous Elements

6.5 References

**7. Methods of Solution and Numerical Examples**

7.1 Introduction to Methods for Solving Equations of Motion
- 7.1.1 Equations of Motion and Constraint Conditions
- 7.1.2 Boundary and Initial Conditions
- 7.1.3 Explicit and Implicit Integration
- 7.1.4 Quasi-Static Equations

7.2 Explicit Integration of Equations of Motion with Constraint Conditions
- 7.2.1 Discretization and Solutions
- 7.2.2 Numerical Instability
- 7.2.3 Computing Contact Nodal Forces
- 7.2.4 Updating Variables for Dynamic Explicit Integration
- 7.2.5 Summary of the Dynamic Explicit Integration Method with Contact Nodal Forces Computed by the Penalty Method
- 7.2.6 Application of the Dynamic Explicit Integration Method to Sheet Metal Forming Analysis

7.3 Implicit Integration of Equations of Motion with Constraint Conditions
- 7.3.1 Newmark's Integration Scheme
- 7.3.2 Newton-Raphson Iteration
- 7.3.3 Computing the Contact Nodal Force Vector by the Direct Method
- 7.3.4 Computing the Contact Nodal Force Vector by the Lagrangian Multiplier Method

7.3.5 Computing the Contact Nodal Force Vector by the Penalty Method
7.3.6 Solving a Large Number of Simultaneous Equations
7.3.7 Convergence of the Newton-Raphson Iteration
7.3.8 Updating Variables for Dynamic Implicit Integration
7.3.9 Summary of the Implicit Integration Method with Contact Nodal Forces Computed by the Penalty Method
7.3.10 Application of Dynamic Implicit Integration to Sheet Metal Forming Analysis
7.4 Quasi-Static Solutions
7.4.1 Equations of Equilibrium and Constraint Conditions
7.4.2 Boundary and Initial Conditions for Quasi-Static Analysis
7.4.3 Quasi-Static Solutions Without an Equilibrium Check
7.4.4 Quasi-Static Solutions with an Equilibrium Check
7.4.5 Summary of the Quasi-Static Method with the Contact Nodal Force Vector Computed by the Penalty Method
7.4.6 Application of the Quasi-Static Method to Sheet Metal Forming Analysis
7.5 Integration of Constitutive Equations
7.5.1 Integration of Rate-Insensitive Plane Stress Constitutive Equations with Isotropic Hardening
7.5.2 Integration of Rate-Insensitive Plane Stress Constitutive Equations with Anisotropic Hardening
7.5.3 Integration of Rate-Insensitive Constitutive Equations with Transverse Shear Strains and Anisotropic Hardening
7.6 Computing Springback
7.6.1 Approximate Method for Computing Springback
7.6.2 Constitutive Equations for Springback Analysis
7.7 Remeshing and Adaptive Meshing
7.7.1 Refinement and Restoration for Triangular Shell Elements
7.7.2 Refinement and Restoration for Quadrilateral Shell Elements
7.8 Numerical Examples of Various Forming Operations
7.8.1 Numerical Examples of Sheets During Binder Wrap
7.8.2 Numerical Examples of Sheets During Stretching or Drawing
7.8.3 Numerical Examples of Springback After Various Forming Operations
7.9 References

**8. Buckling and Wrinkling Analyses**
8.1 Introduction
8.2 Riks' Approach for Solution of Snap-Through and Bifurcation Buckling
8.2.1 Critical Points
8.2.2 Establishment of Governing Equations in the $N + 1$ Dimensional Space
8.2.3 Characteristics of Governing Equations in the $N + 1$ Dimensional Space
8.2.4 Solution for Snap-Through Buckling
8.2.5 Methods to Locate the Secondary Path for Bifurcation Buckling
8.2.6 Method to Locate Critical Points and the Tangent Vector to the Primary Path for Bifurcation Buckling
8.3 Methods to Treat Snap-Through and Bifurcation Buckling in Forming Analyses
8.3.1 Introduction of Artificial Springs at Selected Nodes
8.3.2 Forming Analyses of Snap-Through Buckling and Numerical Examples
8.3.3 Forming Analyses of Bifurcation Buckling and Numerical Examples
8.4 References

**Index**

**About the Authors**