




American Welding Society

The Practical Reference Guide to



Commercial Applications

TABLE OF CONTENTS

	Page No.
Basic Safety Precautions	vi
Introduction.....	1
Welding Aluminum vs. Welding Steel	1
Aluminum Alloy and Temper Designations	1
Effect of Welding on Mechanical Properties of Aluminum Alloys	4
Filler Metal Selection.....	5
Preparing for Welding.....	8
Gas Tungsten Arc Welding (GTAW)	10
Gas Metal Arc Welding (GMAW).....	15
Shielded Metal Arc Welding (SMAW).....	26
Weld Defects—Causes and Cures	26
Solving Problems in Qualifying Weld Procedures	29
Other Publications Available from AWS.....	33

LIST OF TABLES

Figure		Page No.
1	Destination system for wrought alloys	2
2	Designation system for cast alloys.....	2
3	Chemical composition of wrought aluminum filler metals.....	6
4a	Guide to the selection of filler metal for general purpose welding	7
4b	Guide to the selection of filler metal for general purpose welding	7
5	Comparison of filler metals 4043 and 5356.....	8
6	Current ratings for tungsten electrodes for AC GTAW welding with argon shielding.....	14
7	Typical procedures for manual gas tungsten arc welding of butt joints in aluminum with AC and argon shielding	16
8	Typical procedures for manual gas tungsten arc welding of fillet welds in aluminum with AC and argon shielding	16
9	Current carrying capacities of various diameter 2% thoriated electrodes in DC electrode negative welding (DCEN).....	17
10	Typical procedures for manual GTAW of butt joints in aluminum with DCEN and helium shielding in flat position	17
11	Typical procedures for manual GTAW of fillet welds in aluminum with DCEN and helium shielding	17
12	Approximate transition currents for various wire diameters.....	19
13	Typical procedures for gas metal arc welding of groove welds in aluminum alloys with argon shielding	25
14	Typical procedures for gas metal arc welding of fillet welds in aluminum alloys with argon shielding	25

LIST OF FIGURES

Figure		Page No.
1	The relationship of yield strength, amount of cold work, and alloy content	3
2	The "H" temper designations for strain-hardened alloys.....	3
3	Hardness vs. distance for 6061 T4 and T6 in the as-welded (AW) and postweld-aged (PWA) conditions	4
4	Correct pneumatic chisel geometry for backgouging aluminum	11
5	Gas tungsten arc welding equipment arrangement.....	11
6	GTAW showing the proper addition of welding filler rod	15
7	Diagram of gas metal arc welding equipment.....	18
8	Volt/ampere relationship for a constant-current (CC) power supply	19
9	Volt/ampere relationship for a constant-potential (CP) power supply	20
10	The "push" part of a push-pull feeder	21
11	A "pull" gun for a push-pull feeder	22
12	Add-on pull welding gun	22
13	One-pound spool gun for feeding aluminum.....	22
14	Drive rolls and wire guides for feeding aluminum	23
15	Radiograph showing a crater crack.....	26
16	Radiograph showing a longitudinal weld crack	27
17	Radiograph of a weld showing incomplete penetration.....	27
18	Cross section of a weld with incomplete fusion	28
19	Cross section of a weld with excessive porosity	28
20	Radiograph showing tungsten contamination	28
21	Radiograph showing copper contamination.....	29
22	Bent test requirements from AWS D1.2 using plunger type tester	30
23	Bent test requirements for wraparound bend test fixture	31
24	Typical joint geometries for arc welding of aluminum (not to scale)	32