

SAE Manual on Shot Peening

2001 Edition

Table of Contents:

Preface and Acknowledgements

Chapter 1. Introduction

Chapter 2. Description of Process

Chapter 3. Effect of Shot Peening

Chapter 4. Shot Peening Machines

Chapter 5. Peening Media

Chapter 6. Quality Control

Chapter 7. Theory of How Fatigue Properties Are Improved by Shot Peening

Chapter 8. Methods for the Determination of Residual Stresses

Chapter 9. Special Applications

SAE Specifications and Recommended Practices

- J441 JUN93–Cut Wire Shot
- J442 JAN95–Test Strip, Holder, and Gage for Shot Peening
- J443 JAN84–Procedures for Using Standard Shot Peening Test Strip

- J444 MAY93–Cast Shot and Grit Size Specifications for Peening and Cleaning
- J445 APR96–Metallic Shot and Grit Mechanical Testing
- J827 SEP96–High-Carbon Cast-Steel Shot
- J1173 SEP88–Size Classification and Characteristics of Glass Beads for Peening
- J1830 MAY87–Size Classification and Characteristics of Ceramic Shot for Peening
- J2175 JUN91–Specifications for Low Carbon Cast Steel Shot
- J2441 AUG2000–Shot Peening

References

Find the technical resources that you need at sae.org/standards